



**ABANDONED MINE LAND INSPECTION**

PROJECT NAME	PROJECT NO.	GRANT YEAR	REPORT NUMBER
Golden Pond Gob Removal	18302	2018	HNM0009863

CONTRACT INFORMATION		
CONTRACT NUMBER	EXPIRATION DATE	PERCENT OF CONTRACT COMPLETED
C196013	03/31/21	95
CONTRACTOR NAME		ENGINEER NAME
Russell County Reclamation, LLC		SCOTTY COX
SITE CONTACT PERSON: Kevin Large		

INSPECTION DATE	ARRIVAL	DEPARTURE	GROUND CONDITION
10/18/21	08:30 AM	10:00 AM	DRY
10/29/21	03:30 PM	04:30 PM	WET

INSPECTION BY	ATTACHMENTS
MCDONALD-TAYLOR, H.	

**COMMENTS**

Material removal is now complete and the entire area has been covered with a mix of shot rock and soil. The site will be seeded under the 2021 Revegetation Project. Seeding of the structure will occur under the 2021 Revegetation Project. Seeding of the site began on 10/19/21 and concluded on 10/29/21. With completion of the seeding project Project Reclaim Phase II is now eligible for release. Photos of the seeded site are shown below.



**ABANDONED MINE LAND INSPECTION**

